







| NO. | Description | QTY. |
|-----|----------------------|------|
| 1 | Base | 1 |
| 3 | Key 4 x 16 | 2 |
| 4 | Dial | 2 |
| 5 | Hand wheel | 2 |
| 7 | Handle sleeve | 2 |
| 8 | Screw M8 x 55 | 2 |
| 9 | Cap screw M6 x 8 | 7 |
| 10 | Holding plate (1) | 1 |
| 11 | Dust guard cover | 2 |
| 12 | Holding plate(2) | 2 |
| 13 | Ball bearing 8200 | 2 |
| 14 | Washer | 3 |
| 15 | Nut M8 | 6 |
| 16 | Y-axis ruler | 1 |
| 17 | Cap screw M6 x 16 | 4 |
| 18 | Y-axis bearing seat | 1 |
| 19 | Working table | 1 |
| 20 | Y-axis feeding screw | 1 |
| 21 | End cover | 1 |
| 22 | Screw M6 x 10 | 2 |
| 23 | Y-axis screw nut | 1 |
| 24 | Holding plate(3) | 1 |
| 26 | Screw seat | 1 |
| 29 | Nut M6 | 11 |
| 30 | Handle | 4 |
| 31 | Screw M6 x 10 | 2 |
| 32 | Guide finger | 1 |
| 34 | X-axis wedge | 1 |
| 35 | Saddle | 1 |
| 36 | Y-axis wedge | 1 |
| 37 | X-axis screw nut | 1 |
| 38 | Cap screw M6 x 25 | 1 |
| 39 | Fuselage seat | 1 |
| 40 | Spring insert | 3 |
| 41 | Cap screw M10 x 30 | 3 |
| 42 | Guide finger | 2 |
| 43 | Set screw M6 x 22 | 14 |
| 44 | Ruler | 1 |
| 45 | Wedge | 1 |
| 46 | Gear rack | 1 |
| 47 | Cap screw M6 x 12 | 2 |
| 48 | Name plate | 1 |
| 49 | Spindle box | 1 |
| 50 | Gear 14T | 1 |
| 51 | Key 4 x 25 | 1 |

| | | |
|-----|-----------------------|---|
| 52 | Bevel gear 29T | 1 |
| 53 | R etaining ring 12 | 2 |
| 54 | BallΦ5.0 | 2 |
| 55 | Spring 0.8 x 0.8 x 10 | 2 |
| 56 | Screw M6 x 8 | 1 |
| 57 | Handle stock | 1 |
| 58 | Operating lever | 3 |
| 59 | Long handle sleeve | 4 |
| 60 | Cap screw M8 x 25 | 4 |
| 61 | Guide finger | 1 |
| 63 | Spindle box seat | 1 |
| 64 | Wedge | 1 |
| 65 | Limit block | 1 |
| 66 | Wedge | 1 |
| 67 | Ruler | 1 |
| 68 | Column | 1 |
| 69 | Electric box | 1 |
| 70 | Lock nut M24 | 1 |
| 71 | Washer | 1 |
| 72 | Connecting strut | 1 |
| 75 | Screw | 4 |
| 78 | Key 5 x 5 x 40 | 1 |
| 79 | Spindle | 1 |
| 80 | Duplicate gear 21/29T | 1 |
| 81 | Support block | 1 |
| 82 | Screw M5 x 20 | 2 |
| 83 | Pin4 x 15 | 1 |
| 84 | Worm | 1 |
| 85 | Sleeve | 1 |
| 86 | Pin 3 x 12 | 2 |
| 87 | Pin 3 x 12 | 1 |
| 88 | Adjustable union | 1 |
| 89 | Bracket | 1 |
| 90 | Screw M5 x 25 | 2 |
| 91 | Dial | 1 |
| 92 | Damp spring | 3 |
| 93 | Small hand wheel | 1 |
| 94 | Screw M5 x 16 | 1 |
| 95 | Small shaft | 1 |
| 96 | Cover | 1 |
| 97 | Screw M4 x 6 | 2 |
| 98 | Support of dust cover | 1 |
| 99 | Screw M5 x 16 | 2 |
| 100 | Dust guard | 1 |
| 101 | Clamp bolt M6 x 12 | 1 |
| 102 | Upper end washer | 1 |

| | | |
|-----|------------------------------|---|
| 103 | Upper end screw M6 x 16 | 5 |
| 104 | Set screw M6 x 6 | 1 |
| 107 | Handle seat | 1 |
| 108 | Double head bolt M8 x 70 | 1 |
| 110 | Warning label | 1 |
| 111 | Electric box cover | 1 |
| 112 | Electric box | 1 |
| 113 | Shaft (1) | 1 |
| 114 | key4 x 4 x 45 | 1 |
| 116 | Spacing ring | 2 |
| 118 | Spacing ring | 1 |
| 119 | Spindle nut | 1 |
| 120 | key5 x 5 x 30 | 1 |
| 121 | Cap srew M5 x 8 | 6 |
| 122 | Bearing cover | 2 |
| 123 | Ball bearing 80206 | 2 |
| 124 | Name plate | 1 |
| 125 | Fine feeding laebel | 1 |
| 126 | Protecting cover | 1 |
| 127 | Motor | 1 |
| 128 | Motor gear 21/29T | 1 |
| 129 | Intering ring 9.0 | 1 |
| 130 | Motor seat | 1 |
| 131 | Flat screw M6 x 12 | 4 |
| 132 | Round screw M5 x 8 | 1 |
| 133 | Yellow lamp | 1 |
| 134 | Speed control knob | 1 |
| 135 | Green lamp | 1 |
| 136 | Fuse box | 1 |
| 137 | Emergency stop switch | 1 |
| 138 | Gear 30T | 1 |
| 139 | Ball bearing 80101 | 2 |
| 140 | Transmission gear 20/12T | 1 |
| 141 | Fork | 1 |
| 142 | Linking board | 1 |
| 143 | Set screw M5 x 8 | 1 |
| 144 | Self-tapping Screw ST2.9 x 8 | 2 |

| | | |
|------|-------------------|----|
| 145 | H/L label | 1 |
| 146 | Motor cover | 1 |
| 149 | Warming lable | 1 |
| 150 | PC board | 1 |
| 151 | Lock sleeve | 1 |
| 152 | Rotor shaft | 1 |
| 153 | Key 4 x 6 | 2 |
| 154 | Spring support | 1 |
| 155 | Torsion spring | 1 |
| 156 | Cover | 1 |
| 157 | Nut | 1 |
| 158 | Prop | 1 |
| 159 | Supporting shank | 1 |
| 160 | Screw | 1 |
| 161 | Washer | 2 |
| 162 | Washer | 1 |
| 163 | Cover | 1 |
| 164 | Top cover | 1 |
| 200 | Dial seat | 1 |
| 201 | Screw | 4 |
| 202 | Rivet | 10 |
| 203 | Screw | 1 |
| 204 | Screw | 3 |
| 205 | Screw | 2 |
| 206 | Washer | 1 |
| 207 | Screw | 1 |
| 208 | Fixed sleeve | 1 |
| 209 | Washer | 1 |
| 210 | M12 shaft | 1 |
| 211 | B16 Handle | 1 |
| 127A | Key | 1 |
| 127B | Motor gear washer | 1 |
| 2—1 | Cross leadscrew | 1 |
| 39—1 | Shaft | 1 |
| 39—2 | Key | 1 |
| 40—1 | Washer | 3 |